

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2909	Main Str	eet: EASTFIELD_RD	Cross Street: EASTFIELD_RD					Location:	Е
ADA ID: E3796AD99CEB		/pe: Perp	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:		Compliance Description Data Compliance Description						Data	
	SIII .	Remove & Replace Entire Ramp.	N/A Ramp Length (in)		45.0 Yes Ramp Slope (%)		7.7		
All make	1916 3	Remove & Replace Entire Ramp.	No	Ramp Wic	• • • •	46.0	No	Ramp XSlope (%)	2.6
	and the second		N/A	•	()	40.0 N/A	N/A	Flare Type RT	2.0 N/A
	1 and the second		N/A	71		N/A	N/A	Flare Slope RT (%)	N/A
			N/A		versable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A			N/A	N/A	DWS Provided?	N/A
ASS ASS		Surveyor Notes:	N/A	0		N/A	N/A	DWS Contrast?	N/A
	6	, , , , , , , , , , , , , , , , , , ,	N/A	5		N/A	N/A	DWS Length (in)	N/A
		N/A	N/A	0	,	N/A	N/A	DWS Full Width?	N/A N/A
	- The		N/A N/A	-	Slope (%)	N/A	N/A		N/A N/A
1				J -	urb? (Y/N)		N/A	DWS Offset (in)	N/A
			N/A		0	N/A			
	Real Providence	PROW/ADA:	N/A		•	N/A	N/A	Gutter Slope (%)	N/A
	TED .	R304.5.1, R304.5.3	N/A		. ,	N/A	N/A	Gutter X Slope (%)	N/A
			N/A			No	N/A	Painted X Walk2?	N/A
	31104			X Walk 1 [Direction	To SW		X Walk 2 Direction	N/A
			N/A	X Walk 1 \	Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name M	ADISON PARK DR			X Walk 1 S	Slope (%)	1.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 1 X	X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp insi	de XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slop	be (%)	N/A	N/A	Clear Space?	N/A
				Road X SI	ope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstr	uctions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstructio	on Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

