

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Internetion ID: 2025		Cross Street				Lesstien	6
Intersection ID: 2835 Mair	Main Street: CARDINAL_POINT_RD		Cross Street: RED_CLOVER_LN			Location:	S
ADA ID: E3914DBFD7D2 Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance Description D		Data	ata Compliance Description		Data
	Remove & Replace Entire Ramp	N/A	Ramp Length (in)	50.5	No	Ramp Slope (%)	9.8
		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
- Charles - Char		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
CANDINAL POINT AD	The second se	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name RED CLOVER	LN		X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopS	gn		X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	I/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	I/A		Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

**Yes** Surface Condition? (G/P)

Good

