

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14541	1 Main Street: FARM_POND_LN			Cross Street: SNOWCREST_CT				Location:	NE
ADA ID: E50E7805F89D	DD Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1.02	Possible Solutions:						Compliance Description Data	
		Remove & Replace Entire Ram	D.	N/A	Ramp Length (in)	53.0	N/A	Grade Break?	N/A
* In the second	for the	··········	· [• ·	No	Ramp Width (in)	39.0	N/A	Grade Break Slope (%)	0.0
	C. The sea			Yes	Ramp Slope (%)	6.1	N/A	Grade Break XSlope (%)	0.0
the second				No	Ramp XSlope (%)	5.3			
	部につる			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
3	1. 1.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	Line &	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
E Show				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	ST_CT	<i>•</i>		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
the second	and a			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	E uner	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
BAN	F F	R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
JIRD A	1 the second			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
The second secon				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	This - Il			N/A	Painted X Walk1?	No		Road Slope (%)	1.1
Street 1 Name SNO	WCREST CT	-			X Walk 1 Direction	To S		Road X Slope (%)	0.7
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.7	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	17.3

