## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46810	Main Street: ARBOR_VISTA_DR				Street:	CLAUDE_FREEMAN_I	Location:	S				
ADA ID: E5D9322813D	C Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Compliance: I				o Severity Score:	50		
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description		Data Compliance		bliance Description	Data		
	the second second	Remove & Replace	Entire Ram	D.	N/A	Ramp Length LT (in)	65.5	N/A	Ramp Length RT (in)	63.0		
	14 T TO 5			· • ·	Yes	Ramp Width LT (in)	48.0	No	Ramp Width RT (in)	47.5		
APPoo					Yes	Ramp Slope LT (%)	3.4	Yes	Ramp Slope RT (%)	8.3		
A COR	VISTA DR				No	Ramp XSlope LT (%)	4.3	Yes	Ramp XSlope RT (%)	1.9		
de la characteria de la charac					N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	20.0		
JATTA AMAN		-			No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.5		
A real from the		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
Bite LAD		CURB GAP 5.0, LT	RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
		,			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
		1			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
all de la	all / I				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
A DECEMBER		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	1.19 6 5-19	R304.5.1, R304.5.1, R304.2.2,			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
		R304.5.3, R302.7	,,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	of MALLINE				N/A	Shared Landing?	N/A					
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	C TO BER				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	YieldSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1	CLAUDE FREEMAN DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A		
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A		
						X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A		
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	N/A		Clear Space?	N/A		
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
					-			N/A	Any Obstruction?	N/A		
									Obstruction Type			
		Alter and a second		No.						N/A		
				1				N/A	Storm Grate/Utility Hazard?	N/A		
					- Aller			•		1975		

NA Storm Grate/Utility Type N/A Storm Grate/Utility Type N/A Surface Condition? (G/P) Poor Curb Slope (%) N/A