

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11065Main Street:E_35TH_STCross Street:FARLEY_STLocation:SWADA ID: E5E0ABD686FFRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

FARLEY ST

StopSign

E 35TH ST

None

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Comp	liance Description	Data	Comp	iance Description	on	Data
N/A	Ramp Length (in)	58.5	Yes	Ramp Slope (%)		5.0
No	Ramp Width (in)	47.0	No	Ramp XSlope (%	6)	3.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT ((%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversabl	e RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?		N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in))	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width	?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)		N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%))	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2	??	No
	X Walk 1 Direction	To SE		X Walk 2 Direction	on	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width	(in)	N/A
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope ((%)	N/A
	X Walk 1 X Slope (%)	1.7		X Walk 2 X Slop	e (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XW	/alk2?	N/A
	Road Slope (%)	0.4	N/A	Clear Space?		N/A
	Road X Slope (%)	5.4	N/A	Clear Space to >	(Walk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Util	ity Hazard?	N/A
	Obstruction Type			Storm Grate/Util	ity Type	
		N/A				N/A
			Yes	Surface Condition	on? (G/P)	Good





Total Cost:



3200.00