

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49271 Main St	71 Main Street: TWIN_BROOK_DR		t: TOMSIE_I	Location:	w		
			Initial Pass/Fail: Fail Overall Compliance: No				
							13.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Cor	npliance Desc	ription Data	Comp	liance Description	Data
	Remove & Replace Entire Ramp.	N/A	Ramp Leng	th (in) <b>48.0</b>	No	Ramp Slope (%)	11.1
		Yes	Ramp Width	h (in) 48.0	Yes	Ramp XSlope (%)	2.2
		N/A	Flare Type	LT N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope	e LT (%) N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Trave	rsable LT? N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Ler	ngth (in) N/A	N/A	DWS Provided?	N/A
TOWNSIELERING UN	Surveyor Notes:	N/A	Landing Wid	dth (in) N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slo	ope (%) N/A	N/A	DWS Length (in)	N/A
5		N/A	Landing X S	Slope (%) N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A	1	N/A	Landing Cu	rb? (Y/N) N/A	N/A	DWS Offset (in)	N/A
	3.	N/A	Shared Lan	ding? N/A			
V V N R / / has the second	PROW/ADA:	N/A	Gutter Pond	ding? N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2	N/A	Gutter Lip H	lt (in) N/A	N/A	Gutter X Slope (%)	N/A
the second se		N/A	Painted X W	Valk1? No	N/A	Painted X Walk2?	N/A
			X Walk 1 Di	rection To SE		X Walk 2 Direction	N/A
		N/A	X Walk 1 W	idth (in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name TWIN BROOK DR	_		X Walk 1 Sl	ope (%) 0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X	Slope (%) 3.5		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside	e XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope	• (%) N/A	N/A	Clear Space?	N/A
			Road X Slop	pe (%) N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A		,	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction			Storm Grate/Utility Type	
				N/A			N/A

**Yes** Surface Condition? (G/P)

Good

