

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

						_				
Intersection ID: 29723	Main Sti	reet: LANNIER_FALLS_LN	Cross Street: MEDOC_MOUNTAIN_DR					Location:	S	
ADA ID: E7136CE72993	Ramp T	ype: Perp	Initial Pass/Fail: Fail Overall Compliance				ce: No	o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	A 1/2 AND	Possible Solutions:						Compliance Description Data		
A A A	and a strat	Remove & Replace Entire Ramp				48.5	Yes	Ramp Slope (%)	3.5	
	1 1		No	Ramp Widt		47.0	Yes	Ramp XSlope (%)	1.4	
			N/A	•		N/A	N/A	Flare Type RT	N/A	
1 Seal			N/A	51		N/A	N/A	Flare Slope RT (%)	N/A	
	10 000		N/A	Flare Trave	ersable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A		ngth (in)	N/A	N/A	DWS Provided?	N/A	
	(A MAL)	Surveyor Notes:	N/A	0	č ()	N/A	N/A	DWS Contrast?	N/A	
A CARACTER	Carlos Al	N/A	N/A	e e		N/A	N/A	DWS Length (in)	N/A	
	The san		N/A	•	• • • •	N/A	N/A	DWS Full Width?	N/A	
No Allen	the state		N/A			N/A	N/A	DWS Offset (in)	N/A	
	TR SACE		N/A	-	. ,	N/A				
- 115/ Sta		PROW/ADA:	N/A	Gutter Pon	ding?	N/A	N/A	Gutter Slope (%)	N/A	
	A REAL TE	R304.5.1	N/A		•	N/A	N/A	Gutter X Slope (%)	N/A	
		1004.0.1	N/A	•	()	No	N/A	Painted X Walk2?	N/A	
110	S. MER. Strated			X Walk 1 D	irection	To N		X Walk 2 Direction	N/A	
			N/A	X Walk 1 V	/idth (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	LANNIER FALLS LN	-		X Walk 1 S		0.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None			X Walk 1 X	,	3.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N/A		le XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A			Road Slope		N/A	N/A	Clear Space?	N/A	
				Road X Slo		N/A	N/A	Clear Space to XWalk (in)	N/A	
			N/A		,		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	850.00	Obstruction				Storm Grate/Utility Type		
						N/A			N/A	
4										