


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 28536	Main Street: SOUTH_STREAM_BV	Cross Street: W_TYVOLA_RD	Location:	N
ADA ID: E840EF208353	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	60.0
			No	Ramp Width LT (in)	40.0
			Yes	Ramp Slope LT (%)	1.2
			Yes	Ramp XSlope LT (%)	1.0
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1</p>			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.3
				X Walk 1 X Slope (%)	1.0
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			Replace	Curb Slope (%)	10.5
Total Cost:		\$ 1600.00			

