

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.5

1.5

N/A

No

N/A

2.4

0.4

N/A

N/A

N/A

N/A

N/A

Good

To NW

Intersection ID: 13971 Main Street: BALDWIN_AV Cross Street: E_4TH_ST Location: SW

ADA ID: E885F6721EB8 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 30

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

98.5 No

33.0 Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Flare Type RT

Data



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

E 4TH ST None BALDWIN AV Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

LDWIN AV StopSign

Total Cost:

	N/A	Flare Type LT	N/A	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	
	N/A	Landing Length (in)	N/A	N/A	
	N/A	Landing Width (in)	N/A	N/A	
	N/A	Landing Slope (%)	N/A	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	
	N/A	Shared Landing?	N/A		
	N/A	Gutter Ponding?	N/A	N/A	
	N/A	Gutter Lip Ht (in)	1.0	N/A	
	N/A	Painted X Walk1?	No	N/A	
		X Walk 1 Direction	To NE		
	N/A	X Walk 1 Width (in)	N/A	N/A	
		X Walk 1 Slope (%)	2.5		
		X Walk 1 X Slope (%)	2.6		
	N/A	Ramp inside XWalk1?	N/A	N/A	
		Road Slope (%)	4.2	N/A	
		Road X Slope (%)	4.1	N/A	
	N/A	Any Obstructions?	N/A	N/A	
200.00		Obstruction Type			

Compliance Description

Ramp Length (in)

Ramp Width (in)

N/A

No





