cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 10033070 Main Street: NORTH_COMMUNITY_HOUSE_@bss Street: N/A | | | | | | | | Location: | SW |
|---|---------------|-----------------------------|---------|---|-----------------------|-------|--------------------|-----------------------------|------|
| ADA ID: E9109AA8999A | Ramp T | ype: Perp | Initial | nitial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | (And | Possible Solutions: | | | | | liance Description | Data | |
| SP ANNI I I | | Remove & Replace Entire Ram | p. | N/A | Ramp Length (in) | 26.5 | No | Ramp Slope (%) | 10.2 |
| TILLA | 4 1 1 1 1 2 3 | | | Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 1.2 |
| Latter for | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| E Contraction of the second | 1 2 3 2 | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | 11.6 | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| 1 | | 4 | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | 1 S | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | 1.1.1 | Not Found, R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | | κ. | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | | | | N/A | X Walk 1 Width (in) | 112.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | ENTRANCE | | | | X Walk 1 Slope (%) | 5.9 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | Signal | | | | X Walk 1 X Slope (%) | 5.3 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

