

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7876	Main Str	Main Street: BROOKTREE_DR			N/A	Location:	SW			
ADA ID: EA843D709155		Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				33.75	
Codes/Mitigation Info/Possible Solution				Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75 Field Measurements/Component Compliance						
Possible Solutions:			Compliance Description Data Compliance					Data		
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	46.5	1	Grade Break?	N/A	
			•	No	Ramp Width (in)	47.0		Grade Break Slope (%)	0.0	
Val - 1 Hard - Mar				No	Ramp Slope (%)		N/A	Grade Break XSlope (%)	0.0	
	No. X			Yes	Ramp XSlope (%)	0.9				
ETC.	Real			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	6 1 9			N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	0.0	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Mar a	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	and in			N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A	
	Sec. 19 1			N/A	Landing X Slope (%)	0.0		DWS Full Width?	N/A	
	A ILAN	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.1, R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	JAN Y	1004.0.1, 1004.2.2		N/A	Gutter Ponding?		N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	0.8	
Street 1 Name SP	RINGMONT LN	-			X Walk 1 Direction	To E		Road X Slope (%)	5.2	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.2	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A		5 51	N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	22.5	

