

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.0

1.9

N/A

5.3

Nο

Yes

Yes

24.5

Yes

6.5

14.1

0.8

N/A

N/A

Intersection ID: 50592 Main Street: BENDING_BRANCH_RD Cross Street: BRISTLEY_RD Location: SE

ADA ID: EC1410C16FD6 Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

Yes

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Data

48.0

48.0

4.3

Nο

48.0

90.0

2.1

2.2

No No

Yes


No No

0.0

No

To NW

Sloped



Street 1 Name

Stop Condition-Street 2

Street 2 Name

N/A

Stop Condition-Street 1

N/A

Possible Solutions:

Remove & Replace Entire Ramp.
Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.2, R304.5.4

N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? Yes Landing Length (in) Yes Landing Width (in) No Landing Slope (%) No Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? **Gutter Ponding?** Yes Yes Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A N/A Yes 2600.00


N/A

Yes

Compliance Description

Ramp Length (in)

Ramp Width (in)







Total Cost: