

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

11.5

0.9

N/A

Good

Intersection ID: 14182 Main Street: E\_PARK\_AV Cross Street: LYNDHURST\_AV Location: S

ADA ID: EC1F89EC31B4 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

<u>Data</u>

47.0

36.0

N/A

3.0

No

N/A

6.5

5.4

N/A

N/A

N/A

N/A

N/A

To NE



Street 1 Name E PARK AV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2

PROW/ADA: N/A
R304.5.1, R304.2.2 N/A
N/A
N/A

N/A

N/A

Total Cost: \$ 1850.00

N/A Painted X Walk1?
 X Walk 1 Direction

N/A X Walk 1 Width (in)
 X Walk 1 Slope (%)
 X Walk 1 X Slope (%)

N/A Ramp inside XWalk1?
 Road Slope (%)
 Road X Slope (%)

N/A Any Obstructions?
 Obstruction Type

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A





