

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.8

2.7

N/A

5.9

Yes

Yes

Yes

24.0

Yes

0.0

1.8

1.6

N/A

N/A

N/A

N/A

N/A

N/A

Yes

N/A

No

N/A

Good

Intersection ID: 12792 Main Street: E HILL ST **Cross Street: S TRYON ST** Location: Ε

Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 0.25 ADA ID: EC5BE2A31AD5 Ramp Type: Perp

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

Codes/Mitigation Info/Possible Solution

PROW/ADA:

Not Found, R304.5.3



Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

None N/A N/A

> Total Cost: 1850.00

N/A Ramp Length (in) Yes Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? Yes Landing Length (in) Yes Landing Width (in) Yes Landing Slope (%) No Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? **Gutter Ponding?** Yes Yes Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Yes Ramp inside XWalk1? Road Slope (%) Road X Slope (%)

Yes

Any Obstructions?

Obstruction Type

Compliance Description







Field Measurements/Component Compliance

Yes

No

N/A

Yes

N/A

Yes

Yes

Yes

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

Yes

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

79.0

48.0

7.7

Yes

55.0

48.0

1.9

4.0

No

No

No

0.0

Yes

To SW

133.0

1.3

2.3

Yes

N/A

N/A

No

N/A

Sloped