

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.2

2.8

N/A

9.7

No

Yes

Yes

24.0

Yes

4.0

5.1

2.1

N/A

N/A

N/A

N/A

N/A

N/A

Yes

N/A

No

N/A

Good

Main Street: LUPINE CT Intersection ID: 52313 **Cross Street: SNOWBELL CT** Location: NW

Initial Pass/Fail: Pass **Overall Compliance: No** ADA ID: EC732D755E44 Ramp Type: Perp Severity Score: 20.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

Yes

Yes

Yes

Yes

No

No

Yes

N/A

N/A

N/A

N/A

N/A

Yes

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

68.5

48.0

2.6

No

47.5

77.0

1.0

0.2

No

No

Yes

1.8

No

N/A

3.9

2.4

N/A

N/A

N/A

No

N/A

To SW

Sloped

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



SNOWBELL CT Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name N/A

Possible Solutions:	Compl	iance	Description	
Remove & Replace Entire Ramp.	N/A	Ram	c Length (in)	
Remove & Replace Gutter.	Yes	Ramp Width (in)		
	N/A	Flare	Type LT	
	N/A	Flare	Slope LT (%)	
	N/A	Flare	Traversable LT	
	No	Land	ing Length (in)	
Surveyor Notes:	Yes	Land	ing Width (in)	
N/A	Yes	Land	ing Slope (%)	
	Yes	Land	ing X Slope (%	
	N/A	Land	ing Curb? (Y/N	
	N/A	Share	ed Landing?	
PROW/ADA:	No	Gutte	er Ponding?	
Not Found, R304.5.3, R304.2.1,	No	Gutte	er Lip Ht (in)	
R305.2, R302.7, R302.7.2, R304.5.4	N/A	Paint	ed X Walk1?	
		X Wa	lk 1 Direction	
	N/A	X Wa	ılk 1 Width (in)	
		X Wa	ılk 1 Slope (%)	
		X Wa	lk 1 X Slope (%	
	N/A	Ram	o inside XWalk	
		Road	Slope (%)	
		Road	X Slope (%)	

Total Cost:



Yes

2600.00

