

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

14.4

2.1

Intersection ID: 12875 Main Street: DOWNING_ST **Cross Street: ENFIELD RD** Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: EC967410E051 Ramp Type: Perp **Severity Score:** 35

Compliance Description

Ramp Length (in)

Ramp Width (in)

N/A

No

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

45.0 No

45.0 No

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



| Street 1 Name | DOWNING ST |
|-------------------------|------------|
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | N/A |
| Ston Condition-Street 1 | N/A |

| Possible Solutions: | | | | | | |
|--------------------------------|--|--|--|--|--|--|
| Remove & Replace Entire Ramp. | | | | | | |
| • | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| Surveyor Notes: | | | | | | |
| N/A | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| PROW/ADA: | | | | | | |
| Not Found, R304.5.1, R304.2.2, | | | | | | |
| R304.5.3 | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| Ä. | |
|----|--|
| | |



| The state of the s | The state of the s | | | | | | | | | | |
|--|--|-----------------|---|-------|---------|-----|-----------------------|------|-----|-----------------------------|------|
| | | | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | 8 | | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | A CONTRACTOR OF THE PARTY OF TH | Surveyor Notes: | | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| <u>5.</u> | <u>t</u> | N/A | | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| ENFIELD | | | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| 1- | Parking William | | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | | | N/A | Shared Landing? | N/A | | | |
| | | PROW/ADA: | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| The same of the same | | Not Found. | R304.5.1, R30 | 4.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | The file | R304.5.3 | , | | , | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| The state of the s | A Const | | | | | | X Walk 1 Direction | То Е | | X Walk 2 Direction | N/A |
| 16 3 40 F | | | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| eet 1 Name | DOWNING ST | | | | | | X Walk 1 Slope (%) | 1.1 | | X Walk 2 Slope (%) | N/A |
| p Condition-Street 2 | StopSign | | | | | | X Walk 1 X Slope (%) | 6.2 | | X Walk 2 X Slope (%) | N/A |
| eet 2 Name | N/A | | | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| p Condition-Street 1 | N/A | | | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | | \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | | • | N/A | Ĭ | | N/A |
| | | | | | | | | | Yes | Surface Condition? (G/P) | Good |
| | | | | in. | C. West | | | | • | , | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |