

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

35.0

86.5

12.2

5.1

12.3

4.2

N/A

Intersection ID: 10057 Main Street: ANDRILL TR **Cross Street: MADISON AV** W Location: **Overall Compliance: No Severity Score: ADA ID: EDA758ADFE7A** Ramp Type: Combination1 Initial Pass/Fail: Fail 67.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

Yes

No

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Nο

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

42.0

83.0

1.7

8.6 No

83.5

34.0

N/A

No

N/A

To NE



Street 1 Name StopSign Stop Condition-Street 1 MADISON AV N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: LT RP < 5% PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2



Total Cost:





