

ADA ID: EE8BD0677884

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.8

3.5

N/A

Severity Score: 13.75

Main Street: CLANTON RD **Cross Street: S TRYON ST** Location: Intersection ID: 15725 SW Initial Pass/Fail: Fail **Overall Compliance: No**

Codes/Mitigation Info/Possible Solution

Ramp Type: Perp

Total Cost:

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Data

71.0

48.0

N/A

Yes

To E

115.0

0.2

2.7

Yes

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



Street 1 Name	S TRYON ST
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

1 CSSIBIC COIGUION			icia ilic
Possible Solutions:	Compli	ance Des	cription
Remove & Replace Entire Ramp.	N/A	Ramp Len	gth (in)
·	Yes	Ramp Wid	th (in)
	N/A	Flare Type	tT
	N/A	Flare Slop	e LT (%)
	N/A	Flare Trav	ersable L1
	N/A	Landing Lo	ength (in)
Surveyor Notes:	N/A	Landing W	/idth (in)
N/A	N/A	Landing S	lope (%)
	N/A	Landing X	Slope (%)
	N/A	Landing C	urb? (Y/N
	N/A	Shared La	nding?
PROW/ADA:	N/A	Gutter Por	nding?
Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip	Ht (in)
	N/A	Painted X	Walk1?
		X Walk 1 [Direction
	N/A	X Walk 1 \	Vidth (in)
		X Walk 1 S	Slope (%)
		X Walk 1 X	Slope (%
	N/A	Ramp insi	de XWalk′
		Road Slop	e (%)

1.		
		1 man () 1 min ()



N/A

1850.00

N/A N/A Clear Space? N/A N/A N/A Clear Space to XWalk (in) N/A N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good