cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | • | | | | | | | |
|---|--------------------------------------|--------------------------------|----------|---|---|------------|-----------------------------|-----------------------------|------|--|
| Intersection ID: 29389 Main Street: GOLD_PAN_RD | | | | Cross Street: REEDY_PLANTATION_RD | | | | Location: | SE | |
| ADA ID: EE92BE5A766 | ID: EE92BE5A7666 Ramp Type: PerpDiag | | | nitial Pass/Fail: Fail Overall Compliance: No | | | o Severity Score: | 22.5 | | |
| Codes/Mitigation Info/Possible Solution | | | | | Field Measurements/Component Compliance | | | | | |
| 6. 1 1 | in the | Possible Solutions: | | Compliance Description | | Data | Data Compliance Description | | Data | |
| | | Remove & Replace Curb Ra | mp With | N/A | Ramp Length (in) | 48.5 | No | Ramp Slope (%) | 9.2 | |
| | | Two New Directional Ramps | | No | Ramp Width (in) | 47.5 | No | Ramp XSlope (%) | 4.9 | |
| | | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | TID PAN RD | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| 6. | I ame Carlo T | 10/2 | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | |
| | 10 - di | | | N/A | Shared Landing? | N/A | | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | the state of | Not Found, R304.5.1, R304.2.2, | . | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | R304.5.3 | 2.2, | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | 1004.0.0 | | N/A | X Walk 1 Direction | To N | | X Walk 2 Direction | To W | | |
| ACE SCIAN | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | |
| Street 1 Name | Name GOLD PAN RD | | | N/A | | | IN/A | | | |
| | | | | | X Walk 1 Slope (%) | 0.4 4.0 | | X Walk 2 Slope (%) | 5.5 | |
| Stop Condition-Street 2 Street 2 Name | StopSign REEDY PLANTATION RD | | | NI/A | X Walk 1 X Slope (%) | - | | X Walk 2 X Slope (%) | 3.1 | |
| | | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 5.1 | N/A | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | 3.0 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | | N/A | | | N/A | |

es Surface Condition? (G/P)

Good

