

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30179 Main Street: FAIRSTONE_AV Cross Street: VECKMAN_CT Location: NW

ADA ID: EFC22DD66E51 Ramp Type: PerpDiag Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 7.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

FAIRSTONE AV None VECKMAN CT StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.1, R305.1.4, R304.5.4

Total Cost: \$ 3950.00

1 lota modela omente omponent compilation						
	Compliance Description		Data	Data Compliance Description		Data
	N/A	Ramp Length (in)	80.0	Yes	Ramp Slope (%)	5.1
	Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	2.1
	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	1.5	N/A	Flare Slope RT (%)	3.7
	N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	No	Landing Length (in)	45.0	Yes	DWS Provided?	Yes
	Yes	Landing Width (in)	64.0	Yes	DWS Contrast?	Yes
	Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	25.5
	No	Landing X Slope (%)	2.6	No	DWS Full Width?	No
	N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0
	N/A	Shared Landing?	No			
	Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.6
	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.8
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To S		X Walk 2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	4.7
		X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	1.1
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	1.5	N/A	Clear Space?	Yes
		Road X Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A
	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type