


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10027410	Main Street: GOLF_ACRES_DR	Cross Street: N/A	Location: NE
ADA ID: EFC99685C4D5	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Yes</b>	Ramp Length (in)	<b>103.0</b>
			<b>N/A</b>	Ramp Width (in)	<b>48.0</b>
			<b>N/A</b>	Flare Type LT	<b>N/A</b>
			<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>
			<b>N/A</b>	Flare Type RT	<b>N/A</b>
			<b>N/A</b>	Flare Slope RT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable RT?	<b>N/A</b>
			<b>N/A</b>	DWS Provided?	<b>N/A</b>
			<b>N/A</b>	DWS Contrast?	<b>N/A</b>
			<b>N/A</b>	DWS Length (in)	<b>N/A</b>
			<b>N/A</b>	DWS Full Width?	<b>N/A</b>
			<b>N/A</b>	DWS Offset (in)	<b>N/A</b>
			<b>N/A</b>	Gutter Slope (%)	<b>N/A</b>
			<b>N/A</b>	Gutter X Slope (%)	<b>N/A</b>
			<b>N/A</b>	Painted X Walk1?	<b>No</b>
			<b>N/A</b>	X Walk 1 Direction	<b>To W</b>
			<b>N/A</b>	X Walk 2 Direction	<b>To S</b>
			<b>N/A</b>	X Walk 1 Width (in)	<b>N/A</b>
			<b>N/A</b>	X Walk 2 Width (in)	<b>N/A</b>
			<b>N/A</b>	X Walk 1 Slope (%)	<b>2.8</b>
			<b>N/A</b>	X Walk 2 Slope (%)	<b>3.6</b>
			<b>N/A</b>	X Walk 1 X Slope (%)	<b>5.3</b>
			<b>N/A</b>	X Walk 2 X Slope (%)	<b>1.7</b>
			<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>
			<b>N/A</b>	Ramp inside XWalk2?	<b>N/A</b>
			<b>N/A</b>	Road Slope (%)	<b>3.6</b>
			<b>N/A</b>	Clear Space?	<b>N/A</b>
			<b>N/A</b>	Road X Slope (%)	<b>0.3</b>
			<b>N/A</b>	Clear Space to XWalk (in)	<b>N/A</b>
			<b>N/A</b>	Any Obstructions?	<b>N/A</b>
			<b>N/A</b>	Obstruction Type	<b>N/A</b>
			<b>N/A</b>	Storm Grate/Utility Hazard?	<b>N/A</b>
			<b>N/A</b>	Storm Grate/Utility Type	<b>N/A</b>
			<b>N/A</b>	Surface Condition? (G/P)	<b>Good</b>

Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.5.3**

Total Cost: \$ 3200.00

Street 1 Name	<b>ENTRANCE</b>
Stop Condition-Street 2	<b>StopSign</b>
Street 2 Name	<b>Golf Acres</b>
Stop Condition-Street 1	<b>None</b>

