cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28462 Main Street: WESTWINDS_CT					Street	LAWING SCHOOL	Location:	S			
				Cross Street: LAWING_SCHOOL_RD							
ADA ID: F060EB875388 Ramp Type: Directional1			Initial	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	2.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
the second second	7111 30	Possible Solutions:			Compliance Description			Data Compliance Description			
		Remove & Replace Entire	Ram	p.	N/A	Ramp Length (in)	70.0	Yes	Grade Break?	Yes	
		Remove & Replace Gu		•	Yes	Ramp Width (in)	48.0	No	Grade Break Slope (%)	7.9	
					Yes	Ramp Slope (%)	5.3	No	Grade Break XSlope (%)	3.6	
					Yes	Ramp XSlope (%)	1.7				
the second second					Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A	
	B- Carlo			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
E.S	Nº 1	Surveyor Notes:			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
B B C	ap 15 -	N/A			Yes	Landing Length (in)	63.0	Yes	DWS Provided?	Yes	
817	COLOR AND				Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
51 100				Yes	Landing Slope (%)	0.5	Yes	DWS Length (in)	24.5		
			Yes	Landing X Slope (%)	1.6	No	DWS Full Width?	No			
	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	4.0		
	Not Found, R304.5.3, R305.1.4, R305.2		N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	14.0			
Sal Production				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.2		
A second and a second					Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.2	
					N/A	Painted X Walk1?	No		Road Slope (%)	1.1	
Street 1 Name LAWI	NG SCHOOL RD					X Walk 1 Direction	To NW		Road X Slope (%)	0.1	
Stop Condition-Street 1	None					X Walk 1 Width (in)	N/A		Clear Space?	Yes	
Street 2 Name	N/A					X Walk 1 Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	0.1	Yes	Storm Grate/Utility Hazard?	No	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					Yes	Any Obstructions?	No			N/A	
		Total Cost:	\$	2350.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	No	Curb Slope (%)	14.8	

