

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.6

1.6

N/A N/A N/A N/A N/A N/A

N/A N/A N/A N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A Good

Intersection ID: 10032537Main Street: N\_COLLEGE\_STCross Street: N/ALocation:NADA ID: F09C792ACB8FRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Type LT

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

Yes

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Type RT

Data

57.5

47.5

N/A



Street 1 Name

N COLLEGE ST
Stop Condition-Street 2

None
Street 2 Name

N/A
Stop Condition-Street 1

N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
DDOIN/ADA					
PROW/ADA:					
R304.5.1					

Total Cost: \$ 1850.00

N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS Provided?
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
N/A	Shared Landing?	N/A		
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?
	X Walk 1 Direction	To SE		X Walk 2 Direction
N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)
	X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)
	X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?
	Road Slope (%)	N/A	N/A	Clear Space?
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
	Obstruction Type		l	Storm Grate/Utility Type
		N/A		
			Yes	Surface Condition? (G/P)
as de la constitución de la cons	and and			
	- Comment of the second			





