

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25067 Main Street: CARRIAGE_LAKE_DR Cross Street: SMITH_RD Location: SE

ADA ID: F17BC4FB104D Ramp Type: BlendTrans2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 2.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

CARRIAGE LAKE DR StopSign SMITH RD None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent. Remove & Replace
Gutter.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R305.1.4, R305.2,
R304.5.3

Total Cost: \$ 3950.00

	Tiola inducation of the following the first section of the first section						
Complia		ance Description	Data Compliance Description		Data		
	N/A	Ramp Length (in)	99.0	Yes	BlendTrans Slope (%)	2.5	
	Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	2.0	
	N/A	Flare Type LT	None	N/A	Flare Type RT	None	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
	N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
	N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0	
	N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No	
	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	4.5	
	N/A	Shared Landing?	No				
	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.0	
	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.9	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		X Walk 1 Direction	To N		X Walk 2 Direction	To W	
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	0.2	
		X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	1.2	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	1.5		Clear Space?	Yes	
		Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A	
	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	

N/A

Yes No Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

N/A

Good

33.6







Obstruction Type