cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16082	ntersection ID: 16082 Main Street: MEADOW_OAK_DR					OAK_LAKE_BV	Location: SE			
ADA ID: F3A1E9F7AA0F	Ramp Ty	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 0		0
Co	des/Mitigation Info	Possible Solution				Field Measure	ments/C	ompo	nent Compliance	
		Possible Solutions:			Compliance Description			Data Compliance Description		
A CARLENDER	Star Street	Remove & Replace			N/A	Ramp Length LT (in)	47.5	N/A	Ramp Length RT (in)	68.0
	ADOUL OAK DR	Two New Directional Ramps or Equivalent.			Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	59.0
the transfer to the					Yes	Ramp Slope LT (%)	1.4	No	Ramp Slope RT (%)	12.7
The second second				Yes	Ramp XSlope LT (%)	0.9	Yes	Ramp XSlope RT (%)	1.6	
					N/A	Ramp Length (in)	60.5	Yes	Ramp Slope (%)	3.0
B Man					Yes	Ramp Width (in)	69.0	No	Ramp XSlope (%)	7.7
A A A A A A A A A A A A A A A A A A A	AL DEPART	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ि सि	A MARKED	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	And hand				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A BANKIS	The Parks				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	AND AND I	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Not Found, R304.5.3, R304.3.2			3, R304.3.2	2	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and the second of the second	Marine Parts				N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	MEADOW OAK DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None					X Walk 1 Direction	To N		X Walk 2 Direction	To W
Stop Condition-Street 2	OAK LAKE BV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	8.1
						X Walk 1 X Slope (%)	7.0		X Walk 2 X Slope (%)	0.8
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	5.8		Clear Space?	N/A
						Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	N/A
				A Barton				N/A	Any Obstruction?	N/A
									Obstruction Type	
										N/A
39	the second	and the second s			The sea			N/A	Storm Grate/Utility Hazard?	N/A
		the second second	and the	te de	Y Y	a south a			Storm Grate/Utility Type	17/5
660 AM 20		1992		and the second						N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 17.8