## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17581	ersection ID: 17581 Main Street: MCNAIR_RD				Cross Street: RAMA_RD				Е
ADA ID: F3A936CEC839		Ramp Type: PerpDiag				all Compliance: No		Location: o Severity Score:	
	· · · · · · · · · · · · · · · · · · ·								
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description					Data
		Remove & Replace Curb Ram		N/A	Ramp Length (in)	54.0	No	Ramp Slope (%)	8.4
		Two New Directional Ramps o Equivalent.	r	No	Ramp Width (in)		No	Ramp XSlope (%)	7.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 March			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
S S	1 121	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	60	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
B Com	No. of the Party of the			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	200			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 1 1 1 1 1 CM		Not Found, R304.5.1, R304.2.2	2,	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Alles -	R304.5.3	,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Ston All				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
111				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RAMA RD	-			X Walk 1 Slope (%)	10.2		X Walk 2 Slope (%)	3.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	9.5
Street 2 Name	MCNAIR RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	6.4	N/A	Clear Space?	N/A
1 -					Road X Slope (%)	9.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		······ •	5100.00		eset double i jpo	N/A			N/A
						17/4	Yes	Surface Condition? (G/P)	Good
							Tes	Surace Condition? (G/P)	300u

