

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 50998                  | Main Street: S_TRYON_ST |                              |         | Street:  | STEELECROFT_PY        | Location: | NW                          |                             |      |
|---|-------------------------|------------------------------|---------|--|-----------------------|-----------|-----------------------------|-----------------------------|------|
| ADA ID: F3B046E39E82                    | 2 Ramp Type: Perp       |                              |         | Initial Pass/Fail: Fail Overall Compliance: No |                       |           |                             | o Severity Score:           | 12.5 |
| Codes/Mitigation Info/Possible Solution |                         |                              |         | Field Measurements/Component Compliance        |                       |           |                             |                             |      |
|   | 1                       | Possible Solutions:          |         | Compliance Description                         |                       |           | Data Compliance Description |                             |      |
|   |                         | Remove & Replace Entire Ramp |         | N/A  | Ramp Length (in)      | 99.0      | No                          | Ramp Slope (%)              | 11.9 |
|   | 100                     |                              |         | Yes  | Ramp Width (in)       | 48.0      | Yes                         | Ramp XSlope (%)             | 1.2  |
| SOF IN EST                              | H A                     |                              |         | N/A  | Flare Type LT         | N/A       | N/A                         | Flare Type RT               | N/A  |
| A la                                    | 5                       |                              |         | N/A  | Flare Slope LT (%)    | N/A       | N/A                         | Flare Slope RT (%)          | N/A  |
|   |                         |                              |         | N/A  | Flare Traversable LT? | N/A       | N/A                         | Flare Traversable RT?       | N/A  |
|   |                         |                              |         | N/A  | Landing Length (in)   | N/A       | N/A                         | DWS Provided?               | N/A  |
|   |                         | Surveyor Notes:              |         | N/A  | Landing Width (in)    | N/A       | N/A                         | DWS Contrast?               | N/A  |
|   | 2/ 9                    | N/A                          |         | N/A  | Landing Slope (%)     | N/A       | N/A                         | DWS Length (in)             | N/A  |
|   | 1                       |                              |         | N/A  | Landing X Slope (%)   | N/A       | N/A                         | DWS Full Width?             | N/A  |
|   | 1                       |                              |         | N/A  | Landing Curb? (Y/N)   | N/A       | N/A                         | DWS Offset (in)             | N/A  |
|   | <ul> <li>No</li> </ul>  | 8                            |         | N/A  | Shared Landing?       | N/A       |                             |                             |      |
| E E                                     |                         | PROW/ADA:                    |         | N/A  | Gutter Ponding?       | N/A       | N/A                         | Gutter Slope (%)            | N/A  |
|   |                         | R304.2.2                     |         | N/A  | Gutter Lip Ht (in)    | N/A       | N/A                         | Gutter X Slope (%)          | N/A  |
|   |                         |                              |         | N/A  | Painted X Walk1?      | Yes       | N/A                         | Painted X Walk2?            | N/A  |
|   |                         |                              |         |  | X Walk 1 Direction    | To SE     |                             | X Walk 2 Direction          | N/A  |
|   |                         |                              |         | N/A  | X Walk 1 Width (in)   | 112.0     | N/A                         | X Walk 2 Width (in)         | N/A  |
| Street 1 Name W1                        | TRYON ST                |                              |         |  | X Walk 1 Slope (%)    | 2.0       |                             | X Walk 2 Slope (%)          | N/A  |
| Stop Condition-Street 2                 | Signal                  |                              |         |  | X Walk 1 X Slope (%)  | 0.6       |                             | X Walk 2 X Slope (%)        | N/A  |
| Street 2 Name                           | N/A                     |                              |         | N/A  | Ramp inside XWalk1?   | Yes       | N/A                         | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1                 | N/A                     |                              |         |  | Road Slope (%)        | N/A       | N/A                         | Clear Space?                | N/A  |
|   |                         |                              |         |  | Road X Slope (%)      | N/A       | N/A                         | Clear Space to XWalk (in)   | N/A  |
|   |                         |                              |         | N/A  | Any Obstructions?     | N/A       | N/A                         | Storm Grate/Utility Hazard? | N/A  |
|   |                         | Total Cost: \$               | 1850.00 |  | Obstruction Type      |           |                             | Storm Grate/Utility Type    |      |
|   |                         |                              |         |  |                       | N/A       |                             |                             | N/A  |