cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 50942 Main Str	Main Street: CEDAR_WALK_LN		t: DUNAVERTY	Location:	SE		
ADA ID: F54A8138FFDB Ramp Ty	Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance:			o Severity Score:	35
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
A CONTRACTOR OF	Possible Solutions:	Con	Compliance Description		Data Compliance Description		Data
	Remove & Replace Curb Ramp W	/ith N/A	Ramp Length (in	n) 47.0	No	Ramp Slope (%)	12.2
	Two New Directional Ramps or	No	Ramp Width (in)		No	Ramp XSlope (%)	4.2
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (9	%) N/A	N/A	Flare Slope RT (%)	N/A
	5	N/A	Flare Traversable	le LT? N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length ((in) N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A			N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%	%) N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope	e (%) N/A	N/A	DWS Full Width?	N/A
E. C. C.		N/A	•	. ,	N/A	DWS Offset (in)	N/A
3 / 15 / DA 12		N/A	Shared Landing?	? N/A			
1 1 2 1 12	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)) N/A	N/A	Gutter X Slope (%)	N/A
		N/A	,	, ,	N/A	Painted X Walk2?	No
			X Walk 1 Directio	on To NW		X Walk 2 Direction	To SW
		N/A	X Walk 1 Width ((in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CEDAR WALK LN	-		X Walk 1 Slope (. ,		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2 None			X Walk 1 X Slope	. ,		X Walk 2 X Slope (%)	0.3
Street 2 Name DUNAVERTY PL		N/A			N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSign			' Road Slope (%)		N/A	Clear Space?	N/A
			Road X Slope (%		N/A	Clear Space to XWalk (in)	N/A
		N/A	• •	,		Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00	Obstruction Type			Storm Grate/Utility Type	
	•		51	N/A		5 51	N/A

