

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18333 Main Street: BIEMANN_VALLEY_DR Cross Street: JALDENA_DR Location: SE

ADA ID: F71DB6368D7F Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 17.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

JALDENA DR None BIEMANN VALLEY DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Field Measurements/Component Compilance						
Compliance Description		Data	Compl	iance	Description	Data
N/A	Ramp Length (in)	94.0	Yes	Ramp	Slope (%)	7.8
No	Ramp Width (in)	35.0	Yes	Ramp	XSlope (%)	1.8
N/A	Flare Type LT	N/A	N/A Flare Type RT		N/A	
N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)		N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	To W
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.4		X Wa	lk 2 Slope (%)	0.1
	X Walk 1 X Slope (%)	0.4		X Wa	lk 2 X Slope (%)	3.8
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	4.2	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.2	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type