cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



	E 10 Pata
Codes/Mitigation Info/Dessible Solution Eigld Massurements/Commencet Compliance	ata
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance	ata
Possible Solutions: <u>Compliance Description</u> Data Compliance Description Data	
Remove & Replace Curb Ramp With N/A Ramp Length (in) 27.5 Yes BlendTrans Slope (%) 2.	2.7
	3.9
Equivalent. N/A Flare Type LT N/A N/A Flare Type RT N/	N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/	N/A
N/A Landing Length (in) N/A DWS Provided? N/	N/A
Surveyor Notes: N/A Landing Width (in) N/A DWS Contrast? N/	N/A
N/A N/A DWS Length (in) N/	N/A
N/A Landing X Slope (%) N/A N/A DWS Full Width? N/	N/A
N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/	N/A
N/A Shared Landing? N/A	
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/	N/A
Not Found, R304.5.1 N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A	N/A
	N/A
X Walk 1 Direction To W X Walk 2 Direction N/	N/A
X Walk 1 Width (in) N/A X Walk 2 Width (in) N/	N/A
	N/A
	N/A
Street 2 Name N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/	N/A
	N/A
	N/A
	N/A
Total Cost: \$ 3200.00 Obstruction Type Storm Grate/Utility Type	
	N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.2