

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.1

3.0

N/A

Good

Intersection ID: 11913Main Street:MIDLAND\_AVCross Street:BEAUX\_STLocation:WADA ID: F88D3148C998Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

N/A

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

Flare Traversable RT?

Data

72.0

43.0

N/A

N/A

N/A

N/A



Street 1 Name MIDLAND AV
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

PROW/ADA: N/A
Not Found, R304.5.1, R304.5.3 N/A
N/A
N/A

N/A

N/A

Total Cost: \$ 1850.00

N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SE X Walk 2 Direction N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 2.8 X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.9 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) N/A N/A Clear Space? Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type N/A Yes Surface Condition? (G/P)





