## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 19937	Main Str	reet: S_TRYON_ST	Cross Stre	et: THORM	NFIELD_RD	Location:	SW		
ADA ID: F8A6CC96F0ED	Ramp Ty	Initial Pass	/Fail: Pas	s Overall	o Severity Score:	0			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	6.6	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	vith N//	Ramp L	ength (in)	90.0	Yes	Ramp Slope (%)	7.2
		Two New Directional Ramps or	Ye	-	Vidth (in)	48.0	Yes	Ramp XSlope (%)	1.5
		Equivalent. Remove & Replace Gutter.	N//	Flare Ty	/pe LT	Sloped	N/A	Flare Type RT	N/A
			N//	-	ope LT (%)	3.2		Flare Slope RT (%)	7.6
			N//		aversable LT?	No		Flare Traversable RT?	Yes
			Ye		Length (in)	48.0		DWS Provided?	Yes
		Surveyor Notes:	Ye		Width (in)	48.0	Yes	DWS Contrast?	Yes
		N/A	Ye	Ŭ	Slope (%)	2.0	Yes	DWS Length (in)	24.0
		N/A	Ye	Ŭ	X Slope (%)	0.0	Yes	DWS Full Width?	Yes
			N//	5	Curb? (Y/N)		No	DWS Offset (in)	5.5
			N//	5	Landing?	No			0.0
		PROW/ADA:	Ye		Ponding?	No	Yes	Gutter Slope (%)	0.4
			Ye		.ip Ht (in)	0.0	No	Gutter X Slope (%)	3.3
		Not Found, R305.2, R304.5.3	N//		X Walk1?	0.0 No	-	Painted X Walk2?	3.3 No
	1		IN/2		1 Direction	To E	N/A	X Walk 2 Direction	To N
			N/			-	<b>N</b> 1/A		-
			N//		1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	S TRYON ST				1 Slope (%)	1.2		X Walk 2 Slope (%)	4.2
Stop Condition-Street 2	None				1 X Slope (%)	4.3		X Walk 2 X Slope (%)	1.0
Street 2 Name	THORNFIELD RD		N//		side XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				ope (%)	3.8		Clear Space?	Yes
					Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
			Ye	-	structions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 39	950.00	Obstruc	tion Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

