## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



|   |                                | •   |     |         |   |                       |                   |                            |                             |       |  |
|---|--------------------------------|---|-----|---------|---|-----------------------|-------------------|----------------------------|-----------------------------|-------|--|
| Intersection ID: 32316 Main Street: NEW_PROVIDENCE_LN |                                |   |     |         | Street:                                 | WOODCLIFF_CT          | Location:         | S                          |                             |       |  |
| ADA ID: F9CDD60FE37                                   | CDD60FE373 Ramp Type: PerpDiag |   |     |         | Pass/Fa                                 | ail: Fail Overall     | o Severity Score: | 18.75                      |                             |       |  |
| Codes/Mitigation Info/Possible Solution               |                                |   |     |         | Field Measurements/Component Compliance |                       |                   |                            |                             |       |  |
|   |                                | Possible Solutions:   |     |         | Comp                                    | liance Description D  |                   | ata Compliance Description |                             | Data  |  |
|   |                                | Remove & Replace Curb<br>Two New Directional Rar<br>Equivalent. | Ram | o With  | N/A                                     | Ramp Length (in)      | 50.5              | Yes                        | Ramp Slope (%)              | 7.6   |  |
|   |                                |   | •   |         | No                                      | Ramp Width (in)       | 35.5              | No                         | Ramp XSlope (%)             | 3.9   |  |
|   |                                |   |     |         | N/A                                     | Flare Type LT         | N/A               | N/A                        | Flare Type RT               | N/A   |  |
|   |                                |   |     |         | N/A                                     | Flare Slope LT (%)    | N/A               | N/A                        | Flare Slope RT (%)          | N/A   |  |
| Har She   |                                |   |     |         | N/A                                     | Flare Traversable LT? | N/A               | N/A                        | Flare Traversable RT?       | N/A   |  |
|   |                                |   |     | N/A     | Landing Length (in)                     | N/A                   | N/A               | DWS Provided?              | N/A                         |       |  |
| K 🔗   | - ADIGE                        | Surveyor Notes:   |     |         | N/A                                     | Landing Width (in)    | N/A               | N/A                        | DWS Contrast?               | N/A   |  |
| ROW/ADA:<br>Not Found, R304.5.1, R304.5.3             |                                |   |     |         | N/A                                     | Landing Slope (%)     | N/A               | N/A                        | DWS Length (in)             | N/A   |  |
|   |                                |   |     |         | N/A                                     | Landing X Slope (%)   | N/A               | N/A                        | DWS Full Width?             | N/A   |  |
|   |                                |   |     |         | N/A                                     | Landing Curb? (Y/N)   | N/A               | N/A                        | DWS Offset (in)             | N/A   |  |
|   |                                |   |     |         | N/A                                     | Shared Landing?       | N/A               |                            | ( )                         |       |  |
|   |                                |   |     |         | N/A                                     | Gutter Ponding?       | N/A               | N/A                        | Gutter Slope (%)            | N/A   |  |
|   |                                |   |     | 2       | N/A                                     | Gutter Lip Ht (in)    | N/A               | N/A                        | Gutter X Slope (%)          | N/A   |  |
|   |                                |   |     | •       | N/A                                     | Painted X Walk1?      | No                | N/A                        | Painted X Walk2?            | No    |  |
|   |                                |   |     |         |   | X Walk 1 Direction    | To NE             |                            | X Walk 2 Direction          | To NW |  |
|   |                                |   |     |         | N/A                                     | X Walk 1 Width (in)   | N/A               | N/A                        | X Walk 2 Width (in)         | N/A   |  |
| Street 1 Name   | NEW PROVIDENCE LN              | -   |     |         |   | X Walk 1 Slope (%)    | 0.5               |                            | X Walk 2 Slope (%)          | 1.3   |  |
| Stop Condition-Street 2                               | None                           |   |     |         |   | X Walk 1 X Slope (%)  | 3.8               |                            | X Walk 2 X Slope (%)        | 4.2   |  |
| Street 2 Name   | WOODCLIFF CT                   |   |     |         | N/A                                     | Ramp inside XWalk1?   | N/A               | N/A                        | Ramp inside XWalk2?         | N/A   |  |
| Stop Condition-Street 1                               | StopSign                       |   |     |         |   | Road Slope (%)        | 3.6               | N/A                        | Clear Space?                | N/A   |  |
|   |                                |   |     |         |   | Road X Slope (%)      | 5.8               | N/A                        | Clear Space to XWalk (in)   | N/A   |  |
|   |                                |   |     |         | N/A                                     | Any Obstructions?     | N/A               | N/A                        | Storm Grate/Utility Hazard? | N/A   |  |
|   |                                | Total Cost:   | \$  | 3200.00 |   | Obstruction Type      |                   |                            | Storm Grate/Utility Type    |       |  |
|   |                                |   |     |         |   |                       | N/A               |                            |                             | N/A   |  |
|   |                                |   |     |         |   |                       |                   |                            |                             |       |  |

Yes Surface Condition? (G/P) Good

