cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53922	Main Str	eet: ERICA_WOODS_LN	Cross	Street:	PINYON_PINE_LN	Location:	SE		
ADA ID: F9D7549C3DED	Ramp Ty	Ramp Type: PerpDiag			nitial Pass/Fail: Pass Overall Compliance: No				2.75
Codes/Mitigation Info/Possible Solution Field Measurements/Component Co								nent Compliance	
	5	Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	100.0	Yes	Ramp Slope (%)	6.7
		Two New Directional Ramps or		Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	2.2
		Equivalent. Remove & Replace Gutter.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	4.8	N/A	Flare Slope RT (%)	15.1
Solution in the second se				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
The second second	NA A AN			No	Landing Length (in)	47.0	Yes	DWS Provided?	Yes
		Surveyor Notes:		Yes	Landing Width (in)	57.0	Yes	DWS Contrast?	Yes
- Store A		N/A		Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	24.0
A No				Yes	Landing X Slope (%)	0.9	No	DWS Full Width?	No
	Store And			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
	Con and a			N/A	Shared Landing?	No			
Citab.	A A A A A A A A A A A A A A A A A A A	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.3
	A CARLEN AND	Not Found, R304.5.3, R304.2.1, R305.1.4, R305.2		Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.5
	12/12/2011			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PINYON PINE LN				X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	0.9
Street 2 Name	ERICA WOODS LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.8	N/A	Clear Space?	Yes
					Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3950.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

