

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7898Main Street:N\_HOSKINS\_RDCross Street:TENNESSEE\_AVLocation:NEADA ID: FAE4C12086E8Ramp Type:BlendTrans2Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name

TENNESSEE AV
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

| Compliance Description |                       | Data  | Comp | liance Description          | Data |
|------------------------|-----------------------|-------|------|-----------------------------|------|
| N/A                    | Ramp Length (in)      | 109.5 | Yes  | BlendTrans Slope (%)        | 3.6  |
| Yes                    | Ramp Width (in)       | 69.0  | No   | BlendTrans XSlope (%)       | 7.0  |
| N/A                    | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A  |
| N/A                    | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A  |
| N/A                    | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A  |
| N/A                    | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A  |
| N/A                    | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A  |
| N/A                    | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A  |
| N/A                    | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A  |
| N/A                    | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A  |
| N/A                    | Shared Landing?       | N/A   |      |                             |      |
| N/A                    | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A  |
| N/A                    | Gutter Lip Ht (in)    | N/A   | N/A  | Gutter X Slope (%)          | N/A  |
| N/A                    | Painted X Walk1?      | No    | N/A  | Painted X Walk2?            | N/A  |
|                        | X Walk 1 Direction    | To W  |      | X Walk 2 Direction          | N/A  |
|                        | X Walk 1 Width (in)   | N/A   |      | X Walk 2 Width (in)         | N/A  |
|                        | X Walk 1 Slope (%)    | 8.9   |      | X Walk 2 Slope (%)          | N/A  |
|                        | X Walk 1 X Slope (%)  | 2.0   |      | X Walk 2 X Slope (%)        | N/A  |
| N/A                    | Ramp inside XWalk1?   | N/A   | N/A  | Ramp inside XWalk2?         | N/A  |
|                        | Road Slope (%)        | 2.0   |      | Clear Space?                | N/A  |
|                        | Road X Slope (%)      | 8.9   | N/A  | Clear Space to XWalk (in)   | N/A  |
| N/A                    | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A  |
|                        | Obstruction Type      |       | l    | Storm Grate/Utility Type    |      |
|                        |                       | N/A   | l    |                             | N/A  |
|                        |                       |       | Yes  | Surface Condition? (G/P)    | Good |
|                        |                       |       | No   | Curb Slope (%)              | 13.3 |





