

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.6

7.9

N/A

Good

Main Street: CONLAN_CR Cross Street: BRIXHAM HILL AV Intersection ID: 27388 Location: NE **Overall Compliance: No** ADA ID: FB424752D314 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Po

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

59.0

47.0

N/A

No

To W

N/A

3.8

2.9

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)


Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?




Street 1 Name	CONLAN CR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

ossible Solution		Field Me		
Possible Solutions:	Comp	iance Description		
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)		
·	No	Ramp Width (in)		
	N/A	Flare Type LT		
	N/A	Flare Slope LT (%)		
	N/A	Flare Traversable LT		
	N/A	Landing Length (in)		
Surveyor Notes:	N/A	Landing Width (in)		
N/A	N/A	Landing Slope (%)		
	N/A	Landing X Slope (%		
	N/A	Landing Curb? (Y/N		
	N/A	Shared Landing?		
PROW/ADA:	N/A	Gutter Ponding?		
R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)		
	N/A	Painted X Walk1?		
		X Walk 1 Direction		
	N/A	X Walk 1 Width (in)		
		X Walk 1 Slope (%)		
		X Walk 1 X Slope (%		
	N/A	Ramp inside XWalk		
		Road Slope (%)		

in the second			1
		*	•



Total Cost:



N/A

1850.00