cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | · · | | - | | | | | | |
|--|---------------------------------------|--|--------|--|-----------------------|-----------|-----------------------------|-----------------------------|-------|--|
| Intersection ID: 21913 | Main Street: MEANS_CT | | | reet: | WESTHALL_DR | Location: | SW | | | |
| ADA ID: FC00AD8D7506 | Ramp Type: PerpDiag | | | Initial Pass/Fail: Fail Overall Compliance: No | | | o Severity Score: | 37.5 | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| A State of the second s | | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | | |
| REALS OF | 5 | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | /ith | N/A | Ramp Length (in) | 60.0 | No | Ramp Slope (%) | 8.7 | |
| | | | | Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 7.9 | |
| | | | 1 | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| L. | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| S AND SE S | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| Martin and | | 4 | | N/A | Shared Landing? | N/A | | () | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | | Not Found, R304.2.2, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | Not i ouna, Roo4.2.2, Roo4.0.0 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| a the state of the | C C C C C C C C C C C C C C C C C C C | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To SE | |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | |
| Street 1 Name | WESTHALL DR | - | | | X Walk 1 Slope (%) | 4.0 | | X Walk 2 Slope (%) | 0.3 | |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 0.4 | | X Walk 2 X Slope (%) | 3.7 | |
| Street 2 Name | MEANS CT | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 3.4 | N/A | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | 3.7 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ 32 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | - ··· · · · · · | | | | N/A | | | N/A | |
| 1 | | | | | | | | | | |

s Surface Condition? (G/P)

Good

