

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



 Intersection ID: 10709
 Main Street:
 MORSON\_ST
 Cross Street:
 PRYOR\_ST
 Location:
 SW

 ADA ID: FCFB081C24BD
 Ramp Type:
 PerpDiag
 Initial Pass/Fail:
 Fail
 Overall Compliance:
 No
 Severity Score:
 10

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

MORSON ST StopSign PRYOR ST StopSign Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.1, R304.5.3

R ST Bign

Total Cost: \$ 3200.00

Comp	oliance Description	Data	Comp	liance Des	scription	Data
N/A	Ramp Length (in)	86.0	Yes	Ramp Slo	ppe (%)	5.2
No	Ramp Width (in)	47.5	No	Ramp XS	lope (%)	2.3
N/A	Flare Type LT	N/A	N/A	Flare Type	e RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slop	oe RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Trav	versable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Pro	vided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Cor	ntrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Len	gth (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full	Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offs	set (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slo	ope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X S	Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X	Walk2?	No
	X Walk 1 Direction	To E		X Walk 2	Direction	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2	Width (in)	N/A
	X Walk 1 Slope (%)	4.4		X Walk 2	Slope (%)	4.2
	X Walk 1 X Slope (%)	0.1		X Walk 2	X Slope (%)	3.6
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp ins	ide XWalk2?	N/A
	Road Slope (%)	2.4	N/A	Clear Spa	ace?	N/A
	Road X Slope (%)	4.9	N/A	Clear Spa	ace to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Gra	ate/Utility Hazard?	N/A
	Obstruction Type		l	Storm Gra	ate/Utility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good





