

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23117 Main Street: CEDAR_CROSSINGS_DR Cross Street: ERWIN_RD Location: E

ADA ID: FDD8410FB0DC Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name CEDAR CROSSINGS DR
Stop Condition-Street 2 StopSign
Street 2 Name ERWIN RD
Stop Condition-Street 1 None

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.2.2

ign RD one

Total Cost: \$ 3200.00

Compliance Description			Data	Comp	liance	Description	Data
N/A	Ramp	Length (in)	111.0	No	Ram	Slope (%)	12.7
Yes	Ramp '	Width (in)	48.0	Yes	Ram	XSlope (%)	0.1
N/A	Flare T	Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare S	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare T	raversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landin	g Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landin	g Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landin	g Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landin	g X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landin	g Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared	d Landing?	N/A				
N/A	Gutter	Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter	Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted	d X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk	1 Direction	To NW		X Wa	lk 2 Direction	To SW
N/A	X Walk	1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk	1 Slope (%)	2.2		X Wa	lk 2 Slope (%)	1.2
	X Walk	1 X Slope (%)	2.5		X Wa	lk 2 X Slope (%)	0.4
N/A	Ramp	inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road S	Slope (%)	1.9	N/A	Clear	Space?	N/A
	Road >	Slope (%)	1.0	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Ol	ostructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstru	ction Type			Storn	n Grate/Utility Type	
			N/A				N/A

Yes

Surface Condition? (G/P)

Good





