cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 3125	Main Street: JOHNSTON_OEHLER_RD	Cross	Street: MOURNIN	IG_DOVE_LN	Location:	S
ADA ID: 636702BAD7AF	Curb Cut Type: MedianRefuge2	Initial	Pass/Fail: Fail	Overall Compliance	: No Severity Score:	25
Codes/Mit	Field Measurements/Component Compliance					
	Possible Solutions:			ription Data Con		Data
	Remove & Replace Entire Refuge.	_	Yes Refuge 1 Length		Gutter 1 Ponding?	N/A
			Yes Refuge 1 Width (I	· /	Gutter 1 Lip Ht (In)	N/A
			No Refuge 1 Slope (9	%) 6.2 N/A	Gutter 1 Slope (%)	N/A
Contraction of the second	THE LUI		Yes Refuge 1 X Slope			N/A
& TRANDIC			N/A Painted X Walk1?	? No N/A	DWS 1 Provided?	N/A
E Dest			N/A X Walk 1 Direction	on To W N/A	DWS 1 Contrast?	N/A
E E	Surveyor Notes:		N/A X Walk 1 Width (I	In) N/A N/A	DWS 1 Length (In)	N/A
	N/A		N/A Road 1 Slope (%)) 2.2 N/A	DWS 1 Full Width?	N/A
			N/A Road 1 X Slope ((%) 3.0 N/A	DWS 1 Offset (In)	N/A
			Yes Refuge 2 Length	(ln) 47.0 N/A	Gutter 2 Ponding?	N/A
			Yes Refuge 2 Width (I		Gutter 2 Lip Ht (In)	N/A
			No Refuge 2 Slope (%) 7.2 N/A	Gutter 2 Slope (%)	N/A
	PROW/ADA:		Yes Refuge 2 X Slope			N/A
	N/A		N/A Painted X Walk2?	? No N/A	DWS 2 Provided?	N/A
	Contraction of the second s		N/A X Walk 2 Direction	on To E N/A	DWS 2 Contrast?	N/A
			N/A X Walk 2 Width (I	In) N/A N/A	DWS 2 Length (In)	N/A
			N/A Road 2 Slope (%)) 2.2 N/A		N/A
			N/A Road 2 X Slope ((%) 3.1 N/A	DWS 2 Offset (In)	N/A
			N/A Refuge 3 Length	(in) N/A N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 30	00.00	N/A Refuge 3 Width (i		Gutter 3 Lip Ht (in)	N/A
		••••	N/A Refuge 3 Slope (9	,	,	N/A
			N/A Refuge 3 XSlope		1 ()	N/A
			N/A Painted X Walk3?	()		N/A
			N/A X Walk 3 Direction			N/A
			N/A X Walk 3 Width (i			N/A
			N/A Road 3 Slope (%)	,		N/A
			N/A Road 3 XSlope (%)	·		N/A
		1	Yes Any Obstructions		Storm Grate/Utility Hazard?	N/A
		1	N/A Obstruction Type		Storm Grate/Utility Type	
			 -	N/A	<i></i>	N/A
			N/A Surface Condition			
				•		