Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

cole®   **CHARLOTTE**

Intersection ID: 17621	Main Street: CROYDON_RD	Cross Street: RIDGEWOOD_AV	Location:	NE
ADA ID: 1BFA9A716B75	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

	Compliance	Description	Data	Compliance	Description	Data
	N/A	Ramp Length (in)	76.0	N/A	Grade Break?	N/A
	Yes	Ramp Width (in)	50.0	N/A	Grade Break Slope (%)	0.0
	Yes	Ramp Slope (%)	7.0	N/A	Grade Break XSlope (%)	0.0
	No	Ramp XSlope (%)	2.4			
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No		Road Slope (%)	1.2
		X Walk 1 Direction	To W		Road X Slope (%)	2.4
		X Walk 1 Width (in)	N/A		Clear Space?	N/A
		X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
		X Walk 1 X Slope (%)	2.4	N/A	Storm Grate/Utility Hazard?	N/A
	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
	N/A	Any Obstructions?	N/A			N/A
		Obstruction Type		Yes	Surface Condition? (G/P)	Good
				N/A	Curb Slope (%)	17.1

Street 1 Name	**CROYDON RD**
Stop Condition-Street 1	**StopSign**
Street 2 Name	**N/A**
Stop Condition-Street 2	**N/A**

Total Cost: $ 1600.00