# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

**Cole**  
**CHARLOTTE**

| | | | |
|---|---|---|---|
| **Intersection ID: 22310** | **Main Street: OAK_CREEK_DR** | **Cross Street: SARDIS_RD** | **Location: S** |
| **ADA ID: 2324F1FB6060** | **Ramp Type: PerpDiag** | **Initial Pass/Fail: Fail** | **Overall Compliance: No**   **Severity Score: 33.75** |

## Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance



**Possible Solutions:**

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

**Surveyor Notes:**

**N/A**

**PROW/ADA:**

**R304.5.1, R304.2.2, R304.5.3**

| Street 1 Name | **SARDIS RD** |
|---|---|
| Stop Condition-Street 2 | **None** |
| Street 2 Name | **OAK CREEK DR** |
| Stop Condition-Street 1 | **StopSign** |

**Total Cost: $ 3200.00**

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 59.0 | No | Ramp Slope (%) | 11.1 |
| No | Ramp Width (in) | 41.0 | No | Ramp XSlope (%) | 6.2 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 8.9 | | X Walk 2 Slope (%) | 1.3 |
| | X Walk 1 X Slope (%) | 2.3 | | X Walk 2 X Slope (%) | 6.7 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 7.3 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 5.7 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| N/A | | | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |