Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

cole®
CHARLOTTE

Intersection ID: N/A	Main Street: 6TH_ST	Cross Street: N/A	Location: W
ADA ID: 322FDBEDD13B	Ramp Type: Directional1	Initial Pass/Fail: Pass — Overall Compliance: No	Severity Score: 0

Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance

Possible Solutions:

**Remove & Replace Entire Ramp.
Utility Present.**

Surveyor Notes:

GB RUN SLOPE 22%

PROW/ADA:

R304.5.3, R305.2, R302.3, R402.2

Street 1 Name	RR CROSSING
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: $ 6600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	70.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	118.0	No	Grade Break Slope (%)	22.0
Yes	Ramp Slope (%)	3.2	Yes	Grade Break XSlope (%)	1.3
Yes	Ramp XSlope (%)	1.3			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	61.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	118.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	32.0
Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	23.5
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	33.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.1
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.3
N/A	Painted X Walk1?	No		Road Slope (%)	1.2
	X Walk 1 Direction	To SE		Road X Slope (%)	0.1
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.1	No	Storm Grate/Utility Hazard?	Yes
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No		**CDOT ELECTRIC VAULT**	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
N/A			Yes	Curb Slope (%)	0.1