# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

| Intersection ID: 52931 | Main Street: WALTHAM_LN | Cross Street: GRAY_OAK_LN | Location: N |
|---|---|---|---|
| ADA ID: 4D8EDD5CA6DE | Ramp Type: Perp | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 0 |

## Codes/Mitigation Info/Possible Solution / Field Measurements/Component Compliance



**Possible Solutions:**

**Remove & Replace Entire Ramp.**

**Surveyor Notes:**

**N/A**

**PROW/ADA:**

**R304.5.3, R305.2**

| Street 1 Name | WALTHAM LN |
|---|---|
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

Total Cost: $ 1850.00

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 98.5 | Yes | Ramp Slope (%) | 7.8 |
| Yes | Ramp Width (in) | 58.0 | Yes | Ramp XSlope (%) | 0.7 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | 8.8 | Yes | Flare Slope RT (%) | 1.7 |
| N/A | Flare Traversable LT? | Yes | N/A | Flare Traversable RT? | Yes |
| Yes | Landing Length (in) | 61.5 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 58.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 0.9 | Yes | DWS Length (in) | 24.0 |
| No | Landing X Slope (%) | 3.0 | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | No | No | DWS Offset (in) | 5.0 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 2.9 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 0.6 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 2.3 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.8 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | Yes |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| N/A | | | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |