Access Compliance Report
# Public Rights-of-Way
(Curb Ramps)

Intersection ID: 48587	Main Street: STONEY_CREEK_LN	Cross Street: UNIVERSITY_CITY_BV	Location:	SE
ADA ID: 58B4A9E4C674	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%, RT RP < 5%

PROW/ADA:

Not Found, R304.5.1

Street 1 Name: **StopSign**
Stop Condition-Street 1: **STONEY CREEK LN**
Street 2 Name: **N/A**
Stop Condition-Street 2: **N/A**

Total Cost: $ 1800.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	25.0	N/A	Ramp Length RT (in)	22.0
Yes	Ramp Width LT (in)	67.0	Yes	Ramp Width RT (in)	62.0
Yes	Ramp Slope LT (%)	2.0	Yes	Ramp Slope RT (%)	2.8
Yes	Ramp XSlope LT (%)	1.2	Yes	Ramp XSlope RT (%)	0.3
N/A	Ramp Length (in)	101.0	Yes	Ramp Slope (%)	4.1
No	Ramp Width (in)	44.5	Yes	Ramp XSlope (%)	1.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	7.6