# Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Intersection ID: 42988   **Main Street: UNIVERSITY_CITY_BV**   **Cross Street: N/A**   **Location: S**

ADA ID: 9C4BD463DAEE   **Ramp Type: Para**   **Initial Pass/Fail: Fail**   **Overall Compliance: No**   **Severity Score: 12.5**

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Entire Ramp.

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	82.0	N/A	Ramp Length RT (in)	71.0
Yes	Ramp Width LT (in)	88.0	Yes	Ramp Width RT (in)	66.0
Yes	Ramp Slope LT (%)	4.4	No	Ramp Slope RT (%)	8.5
Yes	Ramp XSlope LT (%)	0.6	Yes	Ramp XSlope RT (%)	1.7
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	17.3

Surveyor Notes:

LT RP < 5%

PROW/ADA:

R304.3.2

Street 1 Name	**UNIVERSITY CITY BV**
Stop Condition-Street 1	**Signal**
Street 2 Name	**N/A**
Stop Condition-Street 2	**N/A**

Total Cost: $ 1600.00