# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

**cole**®  CHARLOTTE™

| Intersection ID: 53095 | Main Street: ALEXANDER_DOWD_DR | Cross Street: DEERFIELD_MANOR_DR | Location: W |
|---|---|---|---|
| ADA ID: A76372CBE7B0 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No | Severity Score: 12.5 |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|---|---|



**Possible Solutions:**

**Remove & Replace Entire Ramp.**

**Surveyor Notes:**

**N/A**

**PROW/ADA:**

**Not Found, R304.5.3**

| Street 1 Name | **DEERFIELD MANOR DR** |
|---|---|
| Stop Condition-Street 2 | **StopSign** |
| Street 2 Name | **N/A** |
| Stop Condition-Street 1 | **N/A** |

Total Cost:     $     1850.00

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 94.0 | Yes | Ramp Slope (%) | 6.4 |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 5.2 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.4 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 0.7 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| N/A | | | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |