# Access Compliance Report
# Public Rights-of-Way
# (Curb Ramps)

| Intersection ID: 50708 | Main Street: CELEBRATION_RD | Cross Street: BROTHERLY_LN | Location: | NE |
|---|---|---|---|---|
| ADA ID: C3572D54A25E | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No | Severity Score: 12.5 |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|---|---|



**Possible Solutions:**

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.2.2**

| Street 1 Name | **CELEBRATION RD** |
|---|---|
| Stop Condition-Street 2 | **StopSign** |
| Street 2 Name | **BROTHERLY LN** |
| Stop Condition-Street 1 | **None** |

Total Cost: **$ 3200.00**

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 48.0 | No | Ramp Slope (%) | 9.3 |
| Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 1.3 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To W | | X Walk 2 Direction | To S |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 6.7 | | X Walk 2 Slope (%) | 4.0 |
| | X Walk 1 X Slope (%) | 0.2 | | X Walk 2 X Slope (%) | 6.2 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 4.0 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 5.5 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| N/A | | | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |