# Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Intersection ID: N/A	Main Street: SHARON RD	Cross Street: HAZELTON DR	Location:	SW
ADA ID: DD4F8D4383E9	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

R302.7.2, R304.5.4, R304.5.3

Street 1 Name	**HAZELTON DR**
Stop Condition-Street 1	**StopSign**
Street 2 Name	**N/A**
Stop Condition-Street 2	**N/A**

Total Cost: $ 750.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	164.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	120.0	Yes	Grade Break Slope (%)	2.6
Yes	Ramp Slope (%)	1.6	Yes	Grade Break XSlope (%)	0.3
Yes	Ramp XSlope (%)	0.7			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	120.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.1	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.0	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	1.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	58.0
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	9.5
No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	4.0
N/A	Painted X Walk1?	No		Road Slope (%)	1.3
	X Walk 1 Direction	To N		Road X Slope (%)	4.0
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	4.0	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Yes Curb Slope (%)	1.9