# Access Compliance Report
## Public Rights-of-Way
## (Curb Ramps)

**cole** | **CHARLOTTE**

| | | | |
|---|---|---|---|
| **Intersection ID:** 26283 | **Main Street:** BEVINGTON_RIDGE_RD | **Cross Street:** BEVINGTON_WOODS_LN | **Location:** S |
| **ADA ID:** FE60A76473D2 | **Ramp Type:** BlendTrans1 | **Initial Pass/Fail:** Fail | **Overall Compliance:** No | **Severity Score:** 8.75 |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|---|---|



**Possible Solutions:**

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

**Surveyor Notes:**

**N/A**

**PROW/ADA:**

**Not Found, R304.5.1**

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| N/A | Ramp Length (in) | 47.0 | Yes | BlendTrans Slope (%) | 2.6 |
| No | Ramp Width (in) | 38.0 | Yes | BlendTrans XSlope (%) | 0.2 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 6.8 | | X Walk 2 Slope (%) | 3.5 |
| | X Walk 1 X Slope (%) | 3.1 | | X Walk 2 X Slope (%) | 1.5 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 3.7 | | Clear Space? | N/A |
| | Road X Slope (%) | 3.8 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| N/A | | | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | No | Curb Slope (%) | 17.8 |

| | | |
|---|---|---|
| Street 1 Name | | **BEVINGTON RIDGE RD** |
| Stop Condition-Street 1 | | **None** |
| Street 2 Name | | **BEVINGTON WOODS LN** |
| Stop Condition-Street 2 | | **StopSign** |

Total Cost: **$ 3200.00**